

序号	报告编号	发布日期	结论	影像资料	
1	GX-B1340/21-9-22009~22012	2022. 6. 1	依据AQ1011-2005《煤矿在用主通风机系统安全检测检验规范》进行检验，该通风机合格。		 Two large industrial fans, likely part of a main fan system, are shown. Two workers in blue uniforms and red hard hats stand in front of the fans for scale. The image is taken outdoors with trees in the background. A watermark 'HONOR X10 5G' and '2022.04.16' are visible at the bottom.
2	GX-B1341/21-9-22015	2022. 6. 1	综合判定：合格		 Two workers wearing white protective suits, yellow hard hats, and face masks are standing side-by-side. They are holding equipment, possibly for gas detection or safety monitoring. The background is dark.
3	GX-B1341/21-9-22016	2022. 6. 1	综合判定：合格		 Two workers wearing white protective suits, yellow hard hats, and face masks are standing side-by-side. They are holding equipment, possibly for gas detection or safety monitoring. The background is dark.

4	GX-B1341/21-9-22017	2022. 6. 1	综合判定：合格			
5	GX-B1341/21-9-22015	2022.6.2	合格			
6	GX-B1341/21-9-22016	2022.6.2	合格			

7	GX-B1341/21-9-22017	2022.6.2	合格		 2022.05.08 10:05	
8	GX-B1343/21-9-22008	2022.6.2	/		 2022.05.08 09:25	
9	GX-B1347/21-9-22004	2022.6.2	/		 2022.05.08 09:28	
10	GX-B1370/21-9-22010	2022年6月6日	合格		 239° 西南 大兴煤业 2022年5月17日 10:29:46	

10	GA-B1570/21-9-22010	2022年5月5日	百怡	
----	---------------------	-----------	----	---