


序号	报告编号	发布日期	结论	影像资料
216	GX-B1312/20-6-23029~23032	2023/4/22	所检项目合格	
217	GX-B1312/20-6-23033	2023/4/22	所检项目合格	
218	GX-B1312/20-6-23034~23035	2023/4/22	所检项目合格	

219	GX-B1312/20-6-23036~23037	2023/4/22	所检项目合格	 <p>2023 03 27</p>
220	GX-B1312/20-6-23038~23043	2023/4/22	所检项目合格	 <p>2023 03 28</p>
221	GX-B1312/20-6-23044~23048	2023/4/22	所检项目合格	 <p>2023 03 29</p>

222	GX-B1329/21-6-23051~23057	2023/4/22	所检项目合格	
223	GX-B1350/21-6-23018	2023/4/22	所检项目合格	
224	GX-B1350/21-6-23019	2023/4/22	所检项目合格	

225	GX-B1323/21-6-23018~23025	2023/4/22	所检项目合格	 <p>23 03 26</p>
226	GX-B1323/21-6-23026~23029	2023/4/22	所检项目合格	 <p>2023 03 31</p>
227	GX-B1306/21-6-23001	2023/4/21	所检项目合格	 <p>2023 04 16</p>

228	GX-B1306/21-6-23002	2023/4/21	所检项目合格	
229	GX-B1404/20-6-23003	2023/4/21	<p>所检电网谐波电压总谐波畸变率、各次谐波电压含有率、谐波电流符合 GB/T 14549-1993 《电能质量 公用电网谐波》要求</p>	
230	GX-B1404/20-6-23004	2023/4/21	<p>所检电网谐波电压总谐波畸变率、各次谐波电压含有率、谐波电流符合 GB/T 14549-1994 《电能质量 公用电网谐波》要求</p>	

231	GX-B1404/20-6-23005	2023/4/21	所检电网谐波电压总谐波畸变率、各次谐波电压含有率、谐波电流符合GB/T 14549-1995《电能质量 公用电网谐波》要求			
232	GX-B1404/20-6-23006	2023/4/21	所检电网谐波电压总谐波畸变率、各次谐波电压含有率、谐波电流符合GB/T 14549-1996《电能质量 公用电网谐波》要求			
233	GX-B1495/20-6-23150~23153	2023/4/22	所检项目合格			

234	GX-B1495/20-6-23154~23155	2023/4/22	所检项目合格	
235	GX-B1495/20-6-23156~23169	2023/4/22	所检项目合格	
236	GX-B1495/20-6-23170~23171	2023/4/22	所检项目合格	

237	GX-B1495/20-6-23172~23183	2023/4/22	所检项目合格	 <p>2023 03 27</p>
238	GX-B1495/20-6-23184~23190	2023/4/22	所检项目合格	 <p>2023 03 29</p>
239	GX-B1495/20-6-23095~23098	2023/4/22	所检项目合格	 <p>2023 03 22</p>

240	GX-B1495/20-6-23099~23101	2023/4/22	所检项目合格	
241	GX-B1495/20-6-23102~23105	2023/4/22	所检项目合格	
242	GX-B1495/20-6-23106~23111	2023/4/22	所检项目合格	

243	GX-B1495/20-6-23112~23125	2023/4/22	所检项目合格	
244	GX-B1495/20-6-23126~23127	2023/4/22	所检项目合格	
245	GX-B1495/20-6-23128~23139	2023/4/22	所检项目合格	

246	GX-B1495/20-6-23140~23146	2023/4/22	所检项目合格	
247	GX-B1495/20-6-23147~23149	2023/4/22	所检项目合格	
248	GX-B1352/21-6-23161~23169	2023/4/21	所检项目合格	

249	GX-B1352/21-6-23170~23174	2023/4/21	所检项目合格	
250	GX-B1352/21-6-23175~23186	2023/4/21	所检项目合格	
251	GX-B1352/21-6-23187~23199	2023/4/21	所检项目合格	


252	GX-B1352/21-6-23200~23209	2023/4/21	所检项目合格	
253	GX-B1358/21-6-23007	2023/4/21	所检项目合格	
254	GX-B1358/21-6-23008	2023/4/21	所检项目合格	

255	GX-B1323/21-6-23001~23004	2023/4/21	所检项目合格	
256	GX-B1323/21-6-23005~23012	2023/4/21	所检项目合格	
257	GX-B1323/21-6-23013~23017	2023/4/21	所检项目合格	

258	GX-B1352/21-6-23221~23235	2023/4/21	所检项目合格	
259	GX-B1352/21-6-23210~23220	2023/4/21	所检项目合格	
260	GX-B1352/21-6-23236~23254	2023/4/21	所检项目合格	

261	GX-B1352/21-6-23255~23256	2023/4/21	所检项目合格	
262	GX-B1352/21-6-23257~23292	2023/4/21	所检项目合格	
263	GX-B1359/21-6-23001~23005	2023/4/23	所检项目合格	

264	GX-B1359/21-6-23006~23009	2023/4/23	所检项目合格	
265	GX-B1359/21-6-23010~23011	2023/4/23	所检项目合格	
266	GX-B1359/21-6-23012~23015	2023/4/23	所检项目合格	

267	GX-B1321/20-6-23348~23353	2023/4/22	所检项目合格	
268	GX-B1321/20-6-23354~23356	2023/4/22	所检项目合格	
269	GX-B1495/20-6-23602~23604	2023/4/22	所检项目合格	

270	GX-B1495/20-6-23605~23610	2023/4/22	所检项目合格		 <p>2023 02 21</p>	
271	GX-B1312/20-6-23115~23116	2023/4/22	所检项目合格		 <p>2023 02 23</p>	
272	GX-B1312/20-6-23117~23120	2023/4/22	所检项目合格		 <p>2023 02 21</p>	

273	GX-B1323/21-6-23094~23097	2023/4/22	所检项目合格			
274	GX-B1495/20-6-23578~23584	2023/4/22	所检项目合格			
275	GX-B1495/20-6-23586~23587	2023/4/22	所检项目合格			


276	GX-B1495/20-6-23598~23601	2023/4/22	所检项目合格		 <p>2023.02.23</p>	
277	GX-B1495/20-6-23191~23194	2023/4/22	所检项目合格		 <p>2023.03.22</p>	
278	GX-B1495/20-6-23195~23196	2023/4/22	所检项目合格		 <p>2023.03.23</p>	

279	GX-B1495/20-6-23197~23200	2023/4/22	所检项目合格	
280	GX-B1495/20-6-23201~23202	2023/4/22	所检项目合格	
281	GX-B1495/20-6-23203~23216	2023/4/22	所检项目合格	

282	GX-B1495/20-6-23217~23218	2023/4/22	所检项目合格	
283	GX-B1495/20-6-23219~23230	2023/4/22	所检项目合格	
284	GX-B1495/20-6-23231~23237	2023/4/22	所检项目合格	

285	GX-B1495/20-6-23588~23591	2023/4/22	所检项目合格			
286	GX-B1495/20-6-23592~23597	2023/4/22	所检项目合格			
287	GX-B1312/20-6-23023	2023/4/21	所检项目合格			

288	GX-B1352/21-6-23011~23014	2023/4/21	所检项目合格	
289	GX-B1352/21-6-23015	2023/4/21	所检项目合格	
290	GX-B1520/20-6-23043	2023/4/23	合格	

291	GX-B1520/20-6-23044	2023/4/23	合格	
292	GX-B1359/21-6-23039~23042	2023/4/24	所检项目合格	
293	GX-B1359/21-6-23043~23044	2023/4/24	所检项目合格	

294	GX-B1359/21-6-23045~23046	2023/4/24	所检项目合格	
295	GX-B1563/20-6-23003	2023/4/18	所检项目合格	
296	GX-B1563/20-6-23004	2023/4/18	所检项目合格	

297	GX-B1323/21-6-23058~23061	2023/4/24	本次共检三相交流电动机4台，4台三相交流电动机所检项目合格。	
298	GX-B1323/21-6-23062~23065	2023/4/24	本次共检三相交流电动机4台，4台三相交流电动机所检项目合格。	
299	GX-B1323/21-6-23066~23076	2023/4/24	本次共检三相交流电动机11台，11台三相交流电动机所检项目合格。	

300	GX-B1323/21-6-23077~23083	2023/4/24	本次共检三相交流电动机7台，7台三相交流电动机所检项目合格。			
301	GX-B1323/21-6-23084~23090	2023/4/24	本次共检三相交流电动机7台，7台三相交流电动机所检项目合格。			
302	GX-B1323/21-6-23091~23093	2023/4/24	本次共检三相交流电动机3台，3台三相交流电动机所检项目合格。			

303	GX-B1495/20-6-23393~23402	2023/4/24	本次共检高压防爆开关10台，10台高压防爆开关所检项目合格。	
304	GX-B1495/20-6-23403~23414	2023/4/24	本次共检高压防爆开关12台，12台高压防爆开关所检项目合格。	
305	GX-B1495/20-6-23415~23429	2023/4/24	本次共检高压防爆开关15台，15台高压防爆开关所检项目合格。	


306	GX-B1495/20-6-23430~23443	2023/4/24	本次共检高压防爆开关14台，14台高压防爆开关所检项目合格。	
307	GX-B1495/20-6-23444~23456	2023/4/24	本次共检高压防爆开关13台，13台高压防爆开关所检项目合格。	
308	GX-B1495/20-6-23457~23468	2023/4/24	本次共检高压防爆开关12台，12台高压防爆开关所检项目合格。	

309	GX-B1495/20-6-23469~23485	2023/4/24	本次共检高压防爆开关17台, 17台高压防爆开关所检项目合格。	
310	GX-B1495/20-6-23486~23495	2023/4/24	本次共检高压开关柜10台, 10台高压开关柜所检项目合格。	
311	GX-B1495/20-6-23496~23511	2023/4/24	本次共检高压开关柜16台, 16台高压开关柜所检项目合格。	

312	GX-B1495/20-6-23512~23530	2023/4/24	本次共检高压开关柜19台, 19台高压开关柜所检项目合格。	
313	GX-B1495/20-6-23531~23534	2023/4/24	本次共检高压防爆开关4台, 4台高压防爆开关所检项目合格。	
314	GX-B1495/20-6-23535~23538	2023/4/24	本次共检高压开关柜4台, 4台高压开关柜所检项目合格。	

315	GX-B1495/20-6-23539~23542	2023/4/24	本次共检高压防爆开关4台,4台高压防爆开关所检项目合格。	
316	GX-B1495/20-6-23543~23553	2023/4/24	本次共检高压开关柜11台,11台高压开关柜所检项目合格。	
317	GX-B1495/20-6-23554~23558	2023/4/24	本次共检高压开关柜5台,5台高压开关柜所检项目合格。	

318	GX-B1495/20-6-23559~23570	2023/4/24	本次共检高压开关柜12台, 12台高压开关柜所检项目合格。			
319	GX-B1495/20-6-23571~23577	2023/4/24	本次共检高压开关柜7台, 7台高压开关柜所检项目合格。			
320	GX-B1312/20-6-23086~23087	2023. 4. 21	所检项目合格			

321	GX-B1312/20-6-23088~23098	2023. 4. 21	所检项目合格	
322	GX-B1312/20-6-23099~23101	2023. 4. 21	所检项目合格	
323	GX-B1312/20-6-23102	2023. 4. 21	所检项目合格	

324	GX-B1312/20-6-23103~23106	2023. 4. 21	所检项目合格	
325	GX-B1312/20-6-23107	2023. 4. 21	所检项目合格	
326	GX-B1312/20-6-23108~23112	2023. 4. 21	所检项目合格	

327	GX-B1312/20-6-23113~23114	2023. 4. 21	所检项目合格		 <p>2023 03 21</p>	
328	GX-B1321/20-6-23265~23272	2023/4/23	所检项目合格		 <p>2023 03 23</p>	
329	GX-B1321/20-6-23273~23282	2023/4/23	所检项目合格		 <p>2023 03 23</p>	

330	GX-B1321/20-6-23283~23287	2023/4/23	所检项目合格	
331	GX-B1354/20-6-23005	2023/4/22	电网接地电容电流符合规定	
332	GX-B1598/21-6-23013	2023/4/18	实测钢丝绳有效截面积损失百分比最大为1.00%，小于5%为正常。	

333	GX-B1598/21-6-23012	2023/4/17	实测钢丝绳有效截面积损失百分比最大为0.53%，小于5%为正常。	
334	GX-B1598/21-6-23011	2023/4/17	实测钢丝绳有效截面积损失百分比最大为1.27%，小于5%为正常。	
335	GX-B1598/21-6-23010	2023/4/17	实测钢丝绳有效截面积损失百分比最大为1.52%，小于5%为正常。	

336	GX-B1598/21-6-23009	2023/4/17	实测钢丝绳有效截面积损失百分比最大为0.91%，小于5%为正常。	
337	GX-B1598/21-6-23008	2023/4/17	实测钢丝绳有效截面积损失百分比最大为0.87%，小于5%为正常。	
338	GX-B1321/20-6-23209~23212	2023. 4. 24	所检项目合格。	

339	GX-B1321/20-6-23213~23220	2023. 4. 24	所检项目合格。	
340	GX-B1321/20-6-23221~23226	2023. 4. 24	所检项目合格。	
341	GX-B1321/20-6-23227~23230	2023. 4. 24	所检项目合格。	

342	GX-B1321/20-6-23231~23242	2023. 4. 24	所检项目合格。	 <p>2023 03 25</p>
343	GX-B1321/20-6-23243~23244	2023. 4. 24	所检项目合格。	 <p>2023 03 26</p>
344	GX-B1321/20-6-23245~23258	2023. 4. 24	所检项目合格。	 <p>2023 03 27</p>

345	GX-B1321/20-6-23259~23264	2023. 4. 25	所检项目合格。	 <p>2023 03 29</p>
346	GX-B1328/20-6-23018	2023/4/24	所检项目合格	 <p>2023 02 23</p>
347	GX-B1328/20-6-23019	2023/4/24	所检项目合格	 <p>2023 04 24</p>

348	GX-B1328/20-6-23020	2023/4/25	所检项目合格	
349	GX-B1328/20-6-23021	2023/4/25	所检项目合格	
350	GX-B1328/20-6-23022	2023/4/25	所检项目合格	

351	GX-B1520/20-6-23047	2023/4/25	综合判定：合格	
352	GX-B1520/20-6-23048	2023/4/25	综合判定：合格	
353	GX-B1520/20-6-23049	2023/4/25	综合判定：合格	

354	GX-B1328/20-6-23038	2023/4/20	所检项目合格		 A photograph showing a person in a grey jacket kneeling on a concrete floor in a room. To the left is a window with a wooden frame. On the wall to the right, there are several blue and white charts or notices. The person appears to be using a tool or device on the floor. A yellow date stamp '2023.3.7' is visible in the bottom right corner of the photo.	
355	GX-B1328/20-6-23039	2023/4/20	所检项目合格		 A photograph showing a person in a grey jacket kneeling on a concrete floor in a room. To the left is a window with a wooden frame. On the wall to the right, there are several blue and white charts or notices. The person appears to be using a tool or device on the floor. A yellow date stamp '2023.3.7' is visible in the bottom right corner of the photo.	
356	GX-B1328/20-6-23040	2023/4/20	所检项目合格		 A photograph showing a person in a grey jacket kneeling on a concrete floor in a room. To the left is a window with a wooden frame. On the wall to the right, there are several blue and white charts or notices. The person appears to be using a tool or device on the floor. A yellow date stamp '2023.3.7' is visible in the bottom right corner of the photo.	

357	GX-B1328/20-6-23041	2023/4/20	所检项目合格	
358	GX-B1423/20-6-23336	2023/4/25	综合判定：合格	
359	GX-B1423/20-6-23337	2023/4/25	综合判定：合格	

360	GX-B1423/20-6-23338	2023/4/25	综合判定：合格	 A yellow truck with a green tarp on its bed is parked on a paved area. Three workers in safety gear are standing around the truck. A date stamp '2023 4 9' is visible in the bottom right corner of the photo.
361	GX-B1423/20-6-23339	2023/4/25	综合判定：合格	 A red truck is parked on a paved area. Three workers in safety gear are standing around the truck. A date stamp '2023 4 9' is visible in the bottom right corner of the photo.
362	GX-B1423/20-6-23340	2023/4/25	综合判定：合格	 A yellow truck is parked on a paved area. Two workers in safety gear are standing in front of the truck. A date stamp '2023 4 9' is visible in the bottom right corner of the photo.

363	GX-B1423/20-6-23341	2023/4/25	综合判定：合格	
364	GX-B1423/20-6-23342	2023/4/25	综合判定：合格	
365	GX-B1423/20-6-23343	2023/4/25	综合判定：合格	

366	GX-B1423/20-6-23344	2023/4/25	综合判定：合格	
367	GX-B1423/20-6-23345	2023/4/25	综合判定：合格	
368	GX-B1423/20-6-23346	2023/4/25	综合判定：合格	

369	GX-B1423/20-6-23347	2023/4/25	综合判定：合格	
370	GX-B1423/20-6-23348	2023/4/25	综合判定：合格	
371	GX-B1423/20-6-23349	2023/4/25	综合判定：合格	

372	GX-B1423/20-6-23350	2023/4/25	综合判定：合格	 A yellow truck with the number '12' on its front. Two workers in safety gear stand in front of it. A date stamp '2023 4 10' is visible in the bottom right corner.
373	GX-B1423/20-6-23351	2023/4/25	综合判定：合格	 A yellow truck with the number '30' on its front. Two workers in safety gear stand in front of it. A date stamp '2023 4 10' is visible in the bottom right corner.
374	GX-B1423/20-6-23326	2023/4/25	综合判定：合格	 A yellow truck with the number '6' on its front. Two workers in safety gear stand in front of it. A date stamp '2023 4 6' is visible in the bottom right corner.

375	GX-B1423/20-6-23327	2023/4/25	综合判定：合格	 A yellow truck with a red ribbon on the front. Two workers in safety gear stand in front of it. A timestamp '2023 4 6' is visible in the bottom right corner of the photo.
376	GX-B1423/20-6-23328	2023/4/25	综合判定：合格	 A yellow truck with a red ribbon on the front. Two workers in safety gear stand in front of it. A timestamp '2023 4 6' is visible in the bottom right corner of the photo.
377	GX-B1423/20-6-23329	2023/4/25	综合判定：合格	 A yellow truck with a red ribbon on the front. Two workers in safety gear stand in front of it. A timestamp '2023 4 6' is visible in the bottom right corner of the photo.

378	GX-B1423/20-6-23330	2023/4/25	综合判定：合格	 A photograph showing two men standing in front of a yellow truck. The man on the left is wearing a green safety vest and a red hard hat. The man on the right is wearing a grey jacket and a red hard hat. The truck has the number '66' on its side. A yellow timestamp '2023 4 25' is visible in the bottom right corner of the photo.
379	GX-B1423/20-6-23331	2023/4/25	综合判定：合格	 A photograph showing two men standing in front of a yellow truck. The man on the left is wearing a grey jacket and a red hard hat. The man on the right is wearing a green safety vest and a red hard hat. The truck has the number '36' on its side. A yellow timestamp '2023 4 25' is visible in the bottom right corner of the photo.
380	GX-B1423/20-6-23332	2023/4/25	综合判定：合格	 A photograph showing two men standing in front of a yellow truck. The man on the left is wearing a grey jacket and a red hard hat. The man on the right is wearing a green safety vest and a yellow hard hat. The truck has the number '369' on its side. A yellow timestamp '2023 4 25' is visible in the bottom right corner of the photo.

381	GX-B1423/20-6-23333	2023/4/25	综合判定：合格	
382	GX-B1423/20-6-23334	2023/4/25	综合判定：合格	
383	GX-B1423/20-6-23335	2023/4/25	综合判定：合格	

384	GX-B1423/20-6-23357	2023/4/25	综合判定：合格	
385	GX-B1423/20-6-23358	2023/4/25	综合判定：合格	
386	GX-B1423/20-6-23359	2023/4/25	综合判定：合格	

387	GX-B1423/20-6-23360	2023/4/25	综合判定：合格	
388	GX-B1423/20-6-23361	2023/4/25	综合判定：合格	
389	GX-B1423/20-6-23362	2023/4/25	综合判定：合格	

390	GX-B1423/20-6-23363	2023/4/25	综合判定：合格	
391	GX-B1423/20-6-23364	2023/4/25	综合判定：合格	
392	GX-B1423/20-6-23365	2023/4/25	综合判定：合格	

393	GX-B1423/20-6-23366	2023/4/25	综合判定：合格		
394	GX-B1423/20-6-23367	2023/4/25	综合判定：合格		
395	GX-B1423/20-6-23368	2023/4/25	综合判定：合格		

396	GX-B1520/20-6-23041	2023/4/25	综合判定：合格。	
397	GX-B1520/20-6-23042	2023/4/25	综合判定：合格。	