

序号	报告编号	发布日期	结论	影像资料
311	GX-B1365/20-A-23069	2023/9/22	所检项目全部合格。	 <p>The photograph captures a laboratory setting where two individuals, wearing white lab coats with the '中检公信' (China Inspection and Certification) logo, are engaged in a technical task. They are positioned around a large, complex industrial machine, likely a universal testing machine. One person is focused on adjusting a large circular dial on the machine's control panel, while the other stands to the right, observing the process. The machine features a prominent safety warning sign with Chinese characters and symbols. A date stamp '2023/09/03' is overlaid in the bottom right corner of the image.</p>

序号	报告编号	发布日期	结论	影像资料
312	GX-B1366/20-A-23100	2023/9/22	所检项目全部合格。	

序号	报告编号	发布日期	结论	影像资料
313	GX-B1366/20-A-23101	2023/9/22	所检项目全部合格。	

序号	报告编号	发布日期	结论	影像资料
314	GX-B1365/20-A-23070	2023/9/22	所检项目全部合格。	

序号	报告编号	发布日期	结论	影像资料
315	GX-B1364/22-A-23888	2023/9/25	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
316	GX-B1364/22-A-23872	2023/9/25	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
317	GX-B1364/22-A-23880	2023/9/25	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
318	GX-B1364/22-A-23879	2023/9/25	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
319	GX-B1364/22-A-23878	2023/9/25	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
320	GX-B1364/22-A-23877	2023/9/25	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
321	GX-B1364/22-A-23876	2023/9/25	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
322	GX-B1364/22-A-23875	2023/9/25	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
323	GX-B1364/22-A-23873	2023/9/25	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
324	GX-B1364/22-A-23882	2023/9/25	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
325	GX-B1364/22-A-23881	2023/9/25	成束电线电缆燃烧试验不合格；其余所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
326	GX-B1364/22-A-23883	2023/9/25	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
327	GX-B1364/22-A-23885	2023/9/25	成束电线电缆燃烧试验不合格；其余所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
328	GX-B1364/22-A-23887	2023/9/25	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
329	GX-B1538/22-A-23028	2023/9/25	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
330	GX-B1538/22-A-23026	2023/9/25	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
331	GX-B1368/20-A-23007	2023/9/25	所检项目全部合格。	

序号	报告编号	发布日期	结论	影像资料
332	GX-B1368/20-A-23005	2023/9/25	所检项目全部合格。	

序号	报告编号	发布日期	结论	影像资料
333	GX-B1368/20-A-23006	2023/9/25	所检项目全部合格。	

序号	报告编号	发布日期	结论	影像资料
334	GX-B1366/20-A-23105	2023/9/25	所检项目全部合格。	

序号	报告编号	发布日期	结论	影像资料
335	GX-B1365/20-A-23075	2023/9/25	所检项目全部合格。	

序号	报告编号	发布日期	结论	影像资料
336	GX-B1366/20-A-23107	2023/9/25	所检项目全部合格。	

序号	报告编号	发布日期	结论	影像资料
337	GX-B1366/20-A-23108	2023/9/25	所检项目全部合格。	

序号	报告编号	发布日期	结论	影像资料
338	GX-B1365/20-A-23076	2023/9/25	所检项目全部合格。	

序号	报告编号	发布日期	结论	影像资料
339	GX-B1365/20-A-23077	2023/9/25	所检项目全部合格。	

序号	报告编号	发布日期	结论	影像资料
340	GX-B1363/22-A-23394	2023/9/24	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
341	GX-B1367/22-A-23092	2023/9/24	阻燃性试验不合格；其余所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
342	GX-B1363/22-A-23402	2023/9/24	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
343	GX-B1363/22-A-23403	2023/9/24	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
344	GX-B1363/22-A-23404	2023/9/24	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
345	GX-B1363/22-A-23405	2023/9/24	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
346	GX-B1363/22-A-23406	2023/9/24	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
347	GX-B1363/22-A-23407	2023/9/24	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
347	GX-B1367/22-A-23091	2023/9/24	所检项目全部合格。	

序号	报告编号	发布日期	结论	影像资料
349	GX-B1363/22-A-23398	2023/9/24	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
350	GX-B1363/22-A-23399	2023/9/24	所检项目合格。	 A photograph showing two technicians in light blue work shirts inspecting a large, rusted industrial furnace. The technician on the right is wearing safety glasses and gloves, and is touching the furnace door. A date stamp '2023/09/16' is visible in the bottom right corner of the photo. A green trash bin is visible in the background.

序号	报告编号	发布日期	结论	影像资料
351	GX-B1363/22-A-23397	2023/9/24	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
352	GX-B1363/22-A-23376	2023/9/23	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
353	GX-B1363/22-A-23382	2023/9/23	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
354	GX-B1363/22-A-23384	2023/9/23	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
355	GX-B1363/22-A-23385	2023/9/23	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
356	GX-B1363/22-A-23386	2023/9/23	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
357	GX-B1363/22-A-23387	2023/9/23	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
358	GX-B1363/22-A-23388	2023/9/23	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
359	GX-B1363/22-A-23390	2023/9/23	所检项目合格。	 <p>The photograph shows two men in light blue work shirts inspecting a large, rusted metal industrial furnace. A tall, white-painted metal chimney stack extends from the top of the furnace. One man is on the left, looking at the furnace's door, while the other is on the right, wearing gloves and looking into the furnace. A green trash bin is visible on the left, and a window with a red wall outside is on the right. A date stamp '2023/09/10' is in the bottom right corner of the photo.</p>

序号	报告编号	发布日期	结论	影像资料
360	GX-B1363/22-A-23391	2023/9/23	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
361	GX-B1363/22-A-23392	2023/9/23	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
362	GX-B1363/22-A-23393	2023/9/23	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
363	GX-B1363/22-A-23374	2023/9/23	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
364	GX-B1363/22-A-23375	2023/9/23	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
365	GX-B1363/22-A-23400	2023/9/25	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
366	GX-B1363/20-A-23393	2023/9/23	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
367	GX-B1363/22-A-23386	2023/9/23	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
368	GX-B1363/22-A-23375	2023/9/23	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
369	GX-B1363/22-A-23396	2023/9/27	所检项目合格。	 <p>The photograph shows two technicians in light blue uniforms and dark trousers inspecting a large, industrial-grade furnace. The furnace is a complex, multi-chambered unit with a prominent vertical pipe on top. One technician is wearing gloves and appears to be adjusting or checking a component on the left side of the furnace. The other technician is standing to the right, looking into one of the furnace's chambers. The setting is an indoor laboratory or workshop with a window in the background showing greenery outside. A large green industrial fan is visible on the right side of the frame. A date stamp '2023/09/23' is located in the bottom right corner of the image.</p>

序号	报告编号	发布日期	结论	影像资料
370	GX-B1363/22-A-23409	2023/9/27	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
371	GX-B1364/22-A-23903	2023/9/26	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
372	GX-B1364/22-A-23902	2023/9/26	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
373	GX-B1364/22-A-23901	2023/9/26	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
374	GX-B1364/22-A-23900	2023/9/26	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
375	GX-B1364/22-A-23896	2023/9/26	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
376	GX-B1364/22-A-23897	2023/9/26	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
377	GX-B1364/22-A-23898	2023/9/26	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
378	GX-B1364/22-A-23899	2023/9/26	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
379	GX-B1366/20-A-23103	2023/9/26	所检项目全部合格。	

序号	报告编号	发布日期	结论	影像资料
380	GX-B1365/20-A-23073	2023/9/26	所检项目全部合格。	 <p>2023/09/12</p>

序号	报告编号	发布日期	结论	影像资料
381	GX-B1366/20-A-23109	2023/9/26	所检项目全部合格。	

序号	报告编号	发布日期	结论	影像资料
382	GX-B1365/20-A-23078	2023/9/26	所检项目全部合格。	

序号	报告编号	发布日期	结论	影像资料
383	GX-B1366/20-A-23106	2023/9/26	所检项目全部合格。	

序号	报告编号	发布日期	结论	影像资料
384	GX-B1366/20-A-23104	2023/9/26	所检项目全部合格。	

序号	报告编号	发布日期	结论	影像资料
385	GX-B1365/20-A-23074	2023/9/26	所检项目全部合格。	