

序号	报告编号	发布日期	结论	影像资料
25	GX-B1363/22-A-24401	2024/8/8	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
26	GX-B1363/22-A-24403	2024/8/8	所检项目合格。	

27	GX-B1363/22-A-24409	2024/8/8	所检项目合格。	 2024/08/05
----	---------------------	----------	---------	--

序号	报告编号	发布日期	结论	影像资料
28	GX-B1363/22-A-24408	2024/8/8	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
29	GX-B1363/22-A-24404	2024/8/8	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
30	GX-B1363/22-A-24410	2024/8/9	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
31	GX-B1363/22-A-24411	2024/8/9	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
32	GX-B1363/22-A-24410	2024/8/9	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
33	GX-B1363/22-A-24411	2024/8/9	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
34	GX-B1363/22-A-24405	2024/8/7	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
35	GX-B1363/22-A-24406	2024/8/7	所检项目合格。	 A photograph showing two men in white short-sleeved shirts and dark trousers inspecting a large, rusted industrial furnace. The furnace has a large vertical pipe on top. One man is on the left, looking into the furnace, and the other is on the right, also looking in. A green fan is visible on the right. The date stamp '2024/08/03' is in the bottom right corner of the photo.

序号	报告编号	发布日期	结论	影像资料
36	GX-B1363/22-A-24407	2024/8/7	所检项目合格。	 A photograph showing two male technicians in light blue short-sleeved shirts and dark trousers inspecting a large, rusted industrial machine. The machine has a prominent vertical pipe extending upwards. One technician is on the left, looking at the machine, while the other is on the right, leaning in to inspect a panel. A green trash bin is visible on the left, and a window with a red frame is on the right. A date stamp '2024/08/03' is visible in the bottom right corner of the photo.

序号	报告编号	发布日期	结论	影像资料
37	GX-B1366/20-A-24080	2024/8/6	所检项目全部合格。	

序号	报告编号	发布日期	结论	影像资料
38	GX-B1366/20-A-24079	2024/8/7	所检项目全部合格。	

序号	报告编号	发布日期	结论	影像资料
39	GX-B1365/20-A-24059	2024/8/7	所检项目全部合格。	

序号	报告编号	发布日期	结论	影像资料
40	GX-B1363/22-A-24411	2024/8/9	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
41	GX-B1363/22-A-24410	2024/8/9	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
42	GX-B1363/22-A-24412	2024/8/9	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
43	GX-B1363/22-A-24413	2024/8/9	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
44	GX-B1363/22-A-24412	2024/8/9	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
45	GX-B1366/20-A-24075	2024/8/9	所检项目全部合格。	

序号	报告编号	发布日期	结论	影像资料
46	GX-B1365/20-A-24057	2024/8/9	所检项目全部合格。	

序号	报告编号	发布日期	结论	影像资料
47	GX-B1365/20-A-24060	2024/8/9	所检项目全部合格。	

序号	报告编号	发布日期	结论	影像资料
48	GX-B1366/20-A-24081	2024/8/9	所检项目全部合格。	

序号	报告编号	发布日期	结论	影像资料
49	GX-B1366/20-A-24072	2024/8/9	所检项目全部合格。	

序号	报告编号	发布日期	结论	影像资料
50	GX-B1365/20-A-24055	2024/8/9	所检项目全部合格。	

序号	报告编号	发布日期	结论	影像资料
51	GX-B1365/20-A-24058	2024/8/9	所检项目全部合格。	

序号	报告编号	发布日期	结论	影像资料
52	GX-B1366/20-A-24077	2024/8/9	所检项目全部合格。	

序号	报告编号	发布日期	结论	影像资料
53	GX-B1365/20-A-24078	2024/8/9	所检项目全部合格。	

序号	报告编号	发布日期	结论	影像资料
54	GX-B1365/20-A-24056	2024/8/9	所检项目全部合格。	

序号	报告编号	发布日期	结论	影像资料
55	GX-B1366/20-A-24073	2024/8/9	所检项目全部合格。	

序号	报告编号	发布日期	结论	影像资料
56	GX-B1366/20-A-24074	2024/8/9	所检项目全部合格。	

序号	报告编号	发布日期	结论	影像资料
57	GX-B1363/22-A-24414	2024/8/13	外观质量、阻燃宽度极限偏差、拉伸强度不合格；其余所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
58	GX-B1363/22-A-24418	2024/8/13	所检项目合格。	 A photograph showing two workers in light blue uniforms inspecting a large, rusted industrial furnace or boiler. One worker is on the left, looking at the equipment, while the other is on the right, wearing gloves and touching the furnace. The furnace has yellow warning triangles on its doors. In the background, there is a window with a red frame and a green trash bin. The date '2024/08/10' is printed in the bottom right corner of the photo.

序号	报告编号	发布日期	结论	影像资料
59	GX-B1363/22-A-24414	2024/8/13	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
60	GX-B1363/22-A-24418	2024/8/13	所检项目合格。	 A photograph showing two workers in light blue uniforms inspecting a large, rusted industrial furnace or boiler. One worker is on the left, looking at the equipment, while the other is on the right, wearing gloves and touching the furnace. The furnace has yellow warning triangles on its doors. In the background, there is a window with a red frame and a green trash bin. The date '2024/08/10' is printed in the bottom right corner of the photo.

序号	报告编号	发布日期	结论	影像资料
61	GX-B1364/22-A-24892	2024/8/13	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
62	GX-B1364/22-A-24893	2024/8/13	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
63	GX-B1364/22-A-24894	2024/8/13	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
64	GX-B1364/22-A-24895	2024/8/13	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
65	GX-B1364/22-A-24896	2024/8/13	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
66	GX-B1364/22-A-24897	2024/8/13	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
67	GX-B1364/22-A-24877	2024/8/13	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
68	GX-B1364/22-A-24878	2024/8/13	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
69	GX-B1363/22-A-24419	2024/8/14	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
70	GX-B1363/22-A-24415	2024/8/14	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
71	GX-B1363/22-A-24416	2024/8/14	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
72	GX-B1367/22-A-24057	2024/8/14	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
73	GX-B1367/22-A-24060	2024/8/14	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
74	GX-B1367/22-A-24059	2024/8/14	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
75	GX-B1367/22-A-24058	2024/8/14	所检项目合格。	