

序号	报告编号	发布日期	结论	影像资料
152	GX-B1363/22-A-24713	2024/12/16	所检项目合格。	 A photograph showing two workers in a room, inspecting a large, rusted metal industrial furnace or boiler. One worker is on the left, wearing a grey jacket and black pants, and the other is on the right, wearing a dark jacket and black pants. Both are wearing yellow gloves. The furnace has a large door open, and a white pipe extends from the top. A window with a red frame is visible in the background, and a green fan is on the right. The date '2024/12/12' is printed in the bottom right corner of the photo.

序号	报告编号	发布日期	结论	影像资料
153	GX-B1363/22-A-24714	2024/12/16	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
154	GX-B1364/22-A-241397	2024/12/16	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
155	GX-B1364/22-A-241398	2024/12/16	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
156	GX-B1364/22-A-241399	2024/12/16	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
157	GX-B1364/22-A-241396	2024/12/16	所检项目合格。	

“ 序号	报告编号	发布日期	结论	影像资料
158	GX-B1462/22-A-24014	2024/12/17	所 检 项 目 合 格。	

序号	报告编号	发布日期	结论	影像资料
159	GX-B1364/22-A-241403	2024/12/17	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
160	GX-B1364/22-A-241401	2024/12/16	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
161	GX-B1364/22-A-241402	2024/12/16	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
162	GX-B1364/22-A-241404	2024/12/16	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
163	GX-B1364/22-A-241405	2024/12/16	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
164	GX-B1364/22-A-241406	2024/12/16	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
165	GX-B1364/22-A-241409	2024/12/16	成束电线电缆 燃烧试验不合格；其余所检 项目合格。	

序号	报告编号	发布日期	结论	影像资料
166	GX-B1364/22-A-241392	2024/12/16	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
167	GX-B1364/22-A-241393	2024/12/16	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
168	GX-B1364/22-A-241394	2024/12/16	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
169	GX-B1364/22-A-241395	2024/12/16	所检项目合格。	 A photograph showing two male inspectors in white uniforms with blue logos, standing in a workshop and examining a large, black industrial machine. The machine has a glass-paned door. The background includes a red door and some equipment on the floor. An orange timestamp '2024.12.05' is visible in the bottom right corner of the photo.

序号	报告编号	发布日期	结论	影像资料
170	GX-B1363/22-A-24691	2024/12/17	所检项目合格。	 A photograph showing two workers in a workshop inspecting a large, rusted industrial furnace. One worker is on the left, wearing a dark jacket, and the other is on the right, wearing a light grey jacket and yellow gloves. They are both looking at the furnace's door. The furnace has a large vertical pipe on top and a yellow warning triangle on its side. A green fan is visible on the right. The date '2024/12/11' is printed in the bottom right corner of the photo.

序号	报告编号	发布日期	结论	影像资料
171	GX-B1363/22-A-24675	2024/12/17	所检项目合格。	 A photograph showing two men in a workshop or factory setting. They are standing next to a large, rusted metal machine, possibly a boiler or a large container. One man is wearing a dark jacket and the other is wearing a light grey jacket. They appear to be inspecting or working on the machine. A date stamp '2024/12/11' is visible in the bottom right corner of the image.

序号	报告编号	发布日期	结论	影像资料
172	GX-B1363/22-A-24693	2024/12/17	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
173	GX-B1363/22-A-24711	2024/12/17	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
174	GX-B1363/22-A-24708	2024/12/17	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
175	GX-B1363/22-A-24710	2024/12/17	所检项目合格。	 A photograph showing two workers in a workshop or industrial setting. They are wearing work clothes and gloves, inspecting a large, rusted metal furnace or boiler. A large green industrial fan is visible on the right. The date stamp '2024/12/15' is visible in the bottom right corner of the image.

序号	报告编号	发布日期	结论	影像资料
176	GX-B1363/22-A-24716	2024/12/17	所检项目合格。	 A photograph showing two men in work clothes inspecting a large, open industrial furnace. The furnace is made of metal and has a yellow warning triangle on its front. A large white pipe extends from the top of the furnace. To the right, there is a window with yellow curtains and a green industrial fan. The date '2024/12/14' is printed in the bottom right corner of the photo.

序号	报告编号	发布日期	结论	影像资料
177	GX-B1364/22-A-241412	2024/12/18	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
178	GX-B1364/22-A-241413	2024/12/18	所检项目合格。	 A photograph showing two men in a laboratory or industrial setting. One man is wearing a dark jacket, and the other is wearing a light blue lab coat with a logo. They are standing next to a large piece of industrial equipment, possibly a furnace or a testing chamber, which has a digital display and control panel. The date '2024.12.16' is visible in the bottom right corner of the photo.

序号	报告编号	发布日期	结论	影像资料
179	GX-B1367/22-A-24095	2024/12/17	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
180	GX-B1364/22-A-241419	2024/12/18	所检项目合格。	 A photograph showing two men in a room with industrial equipment. One man, wearing a dark jacket, is looking at a large black machine. The other man, wearing a light grey jacket, is standing next to him, looking at a digital display on the machine. The machine has a red door and a control panel with a screen and buttons. The date '2024.12.16' is visible in the bottom right corner of the photo.

序号	报告编号	发布日期	结论	影像资料
181	GX-B1364/22-A-241420	2024/12/18	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
182	GX-B1364/22-A-241421	2024/12/18	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
183	GX-B1364/22-A-241422	2024/12/18	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
184	GX-B1364/22-A-241423	2024/12/18	所检项目合格。	 A photograph showing two individuals in a laboratory or industrial setting. One person, wearing a dark jacket, is standing with their back to the camera, looking at a large, dark, vertical piece of equipment. The other person, wearing a light-colored lab coat and glasses, is standing next to them, looking at a control panel or screen on the equipment. The equipment has a digital display and various buttons. The background shows a window and some wall-mounted equipment. A timestamp "2024.12.16" is visible in the bottom right corner of the photo.

序号	报告编号	发布日期	结论	影像资料
185	GX-B1364/22-A-241424	2024/12/18	所检项目合格。	 A photograph showing two men in a room with a large, white and black industrial machine. The man on the left is wearing a dark jacket and is looking at the machine. The man on the right is wearing a light-colored jacket and is looking at the control panel of the machine. The control panel has a small screen and several buttons. A date stamp '2024.12.16' is visible in the bottom right corner of the photo.

序号	报告编号	发布日期	结论	影像资料
186	GX-B1364/22-A-241425	2024/12/18	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
187	GX-B1364/22-A-241426	2024/12/18	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
188	GX-B1363/22-A-24721	2024/12/18	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
189	GX-B1363/22-A-24720	2024/12/18	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
190	GX-B1363/22-A-24694	2024/12/19	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
191	GX-B1363/22-A-24719	2024/12/19	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
192	GX-B1363/22-A-24720	2024/12/19	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
193	GX-B1363/22-A-24721	2024/12/19	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
194	GX-B1509/20-A-24045	2024/12/19	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
195	GX-B1509/20-A-24046	2024/12/19	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
196	GX-B1509/20-A-24047	2024/12/19	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
197	GX-B1509/20-A-24048	2024/12/19	所检项目合格。	 A photograph showing a person wearing a light grey lab coat and glasses, leaning over a black desk in a laboratory or office setting. On the desk, there is a white electronic scale, a red hard hat, a yellow folder, and several sheets of paper. The person appears to be working or inspecting the items. A date stamp '2024.12.11' is visible in the bottom right corner of the photo.

序号	报告编号	发布日期	结论	影像资料
198	GX-B1509/20-A-24049	2024/12/19	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
199	GX-B1509/20-A-24050	2024/12/19	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
200	GX-B1613/23-A-24005	2024/12/19	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
201	GX-B1613/23-A-24006	2024/12/19	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
202	GX-B1365/20-A-24098	2024/12/19	所检项目合格。	 A photograph showing a person in a white lab coat operating a large industrial machine. The machine has a prominent circular gauge with a red border and a black needle. The person is adjusting a knob on the machine. The background is a plain white wall. A date stamp '2024.12.10' is visible in the bottom right corner of the image.

序号	报告编号	发布日期	结论	影像资料
203	GX-B1366/20-A-24127	2024/12/19	所检项目合格。	