

序号	报告编号	发布日期	结论	影像资料
23	GX-B1538/22-A-25008	2025/2/8	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
24	GX-B1538/22-A-25009	2025/2/8	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
25	GX-B1538/22-A-25010	2025/2/8	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
26	GX-B1538/22-A-25011	2025/2/8	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
27	GX-B1538/22-A-25012	2025/2/8	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
28	GX-B1538/22-A-25013	2025/2/8	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
29	GX-B1538/22-A-25014	2025/2/8	所检项目合格。	 A photograph showing two men in a room, likely a laboratory or workshop, inspecting a piece of equipment. The man on the left is wearing a light-colored jacket with 'GPR' visible on the back. The man on the right is wearing a dark jacket. They are looking at a dark, rectangular object, possibly a control panel or a piece of machinery. The room has white walls and a red door in the background. A timestamp '2025.02.08' is visible in the bottom right corner of the photo.

序号	报告编号	发布日期	结论	影像资料
30	GX-B1538/22-A-25015	2025/2/8	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
31	GX-B1538/22-A-25016	2025/2/8	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
32	GX-B1538/22-A-25017	2025/2/8	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
33	GX-B1538/22-A-25018	2025/2/8	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
34	GX-B1538/22-A-25019	2025/2/8	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
35	GX-B1538/22-A-25020	2025/2/8	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
36	GX-B1538/22-A-25021	2025/2/8	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
37	GX-B1538/22-A-25022	2025/2/8	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
38	GX-B1538/22-A-25023	2025/2/8	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
39	GX-B1538/22-A-25024	2025/2/8	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
40	GX-B1538/22-A-25025	2025/2/8	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
41	GX-B1538/22-A-25026	2025/2/8	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
42	GX-B1538/22-A-25027	2025/2/8	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
43	GX-B1364/22-A-25134	2025/2/12	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
44	GX-B1364/22-A-25135	2025/2/12	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
45	GX-B1364/22-A-25136	2025/2/12	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
46	GX-B1364/22-A-25130	2025/2/12	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
47	GX-B1364/22-A-25129	2025/2/12	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
48	GX-B1364/22-A-25103	2025/2/12	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
49	GX-B1364/22-A-25133	2025/2/12	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
50	GX-B1364/22-A-25132	2025/2/12	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
51	GX-B1364/22-A-25131	2025/2/12	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
52	GX-B1364/22-A-25094	2025/2/12	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
53	GX-B1363/22-A-25058	2025/2/12	所检项目合格。	 <p>The photograph shows two men in dark jackets and work clothes inspecting a large, rusted metal industrial furnace or boiler. One man is wearing yellow gloves and is reaching into the open door of the furnace. The furnace has a yellow warning triangle on its front. To the right, there is a window and a green floor fan. A date stamp '2025.02.' is visible in the bottom right corner of the photo.</p>

序号	报告编号	发布日期	结论	影像资料
54	GX-B1363/22-A-25055	2025/2/12	所检项目合格。	 A photograph showing two technicians in dark jackets and gloves inspecting a large, rusted industrial furnace or boiler. The furnace has a yellow warning triangle on its front. A green floor fan is visible to the right. The scene is indoors, near a window with a view of trees. A timestamp '2025.02.' is visible in the bottom right corner of the photo.

序号	报告编号	发布日期	结论	影像资料
55	GX-B1363/22-A-25054	2025/2/11	所检项目合格。	 A photograph showing two men in dark jackets and gloves inspecting a large, rusted metal industrial furnace or boiler. The furnace has a yellow radiation warning symbol on its side. The scene is indoors, with a window in the background and a green floor fan to the right. An orange timestamp '2025.02.' is visible in the bottom right corner of the photo.

序号	报告编号	发布日期	结论	影像资料
56	GX-B1363/22-A-25053	2025/2/11	所检项目合格。	 <p>The photograph shows two individuals in a room, likely a workshop or industrial setting, inspecting a large, rusted metal furnace or boiler. One person is wearing a dark jacket and the other is wearing a blue jacket and yellow gloves. A large green industrial fan is visible on the right side of the frame. The date '2025.02.11' is printed in orange in the bottom right corner of the image.</p>

序号	报告编号	发布日期	结论	影像资料
57	GX-B1363/22-A-25052	2025/2/11	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
58	GX-B1363/22-A-25056	2025/2/12	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
59	GX-B1363/22-A-25057	2025/2/14	所检项目合格。	 A photograph showing two men in dark jackets and yellow gloves inspecting a large, rusted metal boiler or furnace. The boiler has a vertical pipe on top and a door with a yellow warning triangle. The scene is indoors, with a window and a green fan visible in the background.

序号	报告编号	发布日期	结论	影像资料
60	GX-B1363/22-A-25060	2025/2/14	所检项目合格。	 A photograph showing two individuals in a workshop or industrial setting. They are inspecting a large, heavy-duty metal cabinet or enclosure. The cabinet has a prominent radiation warning symbol (a yellow triangle with a black border and a black exclamation mark) on its front panel. One person, wearing a grey jacket and yellow gloves, is looking into the open cabinet. The other person, wearing a dark jacket, is also looking into the cabinet. The background shows a window with a view of the outdoors. A date stamp '2025.02.' is visible in the bottom right corner of the image.

序号	报告编号	发布日期	结论	影像资料
61	GX-B1364/22-A-25137	2025/2/14	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
62	GX-B1364/22-A-25138	2025/2/14	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
63	GX-B1364/22-A-25139	2025/2/14	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
64	GX-B1364/22-A-25140	2025/2/14	成束电线电缆燃烧试验不合格；其余所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
65	GX-B1364/22-A-25141	2025/2/14	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
66	GX-B1364/22-A-25142	2025/2/14	成束电线电缆燃烧试验不合格；其余所检项目合格。	 A photograph showing two individuals in a laboratory or industrial setting. The person on the left is wearing a light-colored jacket with the logo '中检公信' (Zhongjian Gongxin) on the back. They are both looking towards a piece of equipment or a panel. The person on the right is wearing a dark jacket. The background includes a red door and a window. A date stamp '2025.02.' is visible in the bottom right corner of the photo.

序号	报告编号	发布日期	结论	影像资料
67	GX-B1364/22-A-25143	2025/2/14	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
68	GX-B1364/22-A-25144	2025/2/14	所检项目合格。	