



序号	报告编号	发布日期	结论	影像资料
50	GX-B1303/21-4-25001	2025/2/24	所检项目合格。	 A photograph showing four workers wearing hard hats (two orange, two red) and work clothes, inspecting an open electrical cabinet. The cabinet is white with a green interior. A red date stamp '2025 2 18' is visible in the bottom right corner of the image.
51	GX-B1310/21-4-25012	2025. 2. 26	符合标准要求。	 A photograph showing a worker in a red hard hat and blue work clothes inspecting a large blue industrial machine. The machine has a yellow door. A red date stamp '2025 2 17' is visible in the bottom right corner of the image.

52	GX-B1310/21-4-225013	2025. 2. 26	符合标准要求。	
53	GX-B1310/21-4-25014	2025. 2. 26	符合标准要求。	
54	GX-B1310/21-4-25015	2025. 2. 26	符合标准要求。	

55	GX-B1310/21-4-25016	2025. 2. 26	符合标准要求。	
56	GX-B1310/21-4-25017	2025. 2. 26	符合标准要求。	
57	GX-B1310/21-4-25018	2025. 2. 26	符合标准要求。	

58	GX-B1310/21-4-25019	2025. 2. 26	符合标准要求。	
59	GX-B1310/21-4-25020	2025. 2. 26	符合标准要求。	
60	GX-B1310/21-4-25021	2025. 2. 26	符合标准要求。	

61	GX-B1310/21-4-25022	2025. 2. 26	符合标准要求。	
62	GX-B1310/21-4-25023	2025. 2. 26	符合标准要求。	
63	GX-B1310/21-4-25024	2025. 2. 26	符合标准要求。	

64	GX-B1310/21-4-25025	2025. 2. 26	符合标准要求。	
65	GX-B1428/21-4-25026	2025. 2. 26	符合标准要求。	
66	GX-B1428/21-4-25027	2025. 2. 26	符合标准要求。	

67	GX-B1428/21-4-25028	2025. 2. 26	符合标准要求。	
68	GX-B1428/21-4-25029	2025. 2. 26	符合标准要求。	
69	GX-B1350/21-4-25004	2025/2/27	本次共检接地装置3处，3处所检项目合格。	

70	GX-B1324/21-4-25001	2025/2/27	本次共检三相交流电动机1台，1台三相交流电动机所检项目合格。	
----	---------------------	-----------	--------------------------------	---