

序号	报告编号	发布日期	结论	影像资料
345	GX-B1354/20-6-25002	2025/4/18	电网接地电容电流符合规定。	
346	GX-B1354/20-6-25003	2025/4/18	电网接地电容电流符合规定。	
347	GX-B1354/20-6-25004	2025/4/18	电网接地电容电流符合规定。	

348	GX-B1404/20-6-25003	2025/4/18	所检电网谐波电压总谐波畸变率、各次谐波电压含有率、谐波电流符合GB/T 14549-1993 《电能质量 公用电网谐波》要求。	
349	GX-B1404/20-6-25004	2025/4/18	所检电网谐波电压总谐波畸变率、各次谐波电压含有率、谐波电流符合GB/T 14549-1993 《电能质量 公用电网谐波》要求。	
350	GX-B1404/20-6-25005	2025/4/18	所检电网谐波电压总谐波畸变率、各次谐波电压含有率、谐波电流符合GB/T 14549-1993 《电能质量 公用电网谐波》要求。	

351	GX-B1404/20-6-25006	2025/4/18	所检电网谐波电压总谐波畸变率、各次谐波电压含有率、谐波电流符合GB/T 14549-1993 《电能质量 公用电网谐波》要求。			
352	GX-B1404/20-6-25007	2025/4/18	所检电网谐波电压总谐波畸变率、各次谐波电压含有率、谐波电流符合GB/T 14549-1993 《电能质量 公用电网谐波》要求。			
353	GX-B1404/20-6-25008	2025/4/18	所检电网谐波电压总谐波畸变率、各次谐波电压含有率、谐波电流符合GB/T 14549-1993 《电能质量 公用电网谐波》要求。			

354	GX-B1451/20-6-25495~25509	2025/4/17	本次共检高压开关柜15台, 15台高压开关柜所检项目合格。 。	
355	GX-B1304/21-6-25013	2025/4/25	综合判定：合格	
356	GX-B1329/21-6-25084~25087	2025/4/16	本次共检氧化锌避雷器4组, 4组氧化锌避雷器所检项目合格。	

357	GX-B1329/21-6-25088~25092	2025/4/16	本次共检氧化锌避雷器5组，5组氧化锌避雷器所检项目合格。	
358	GX-B1304/21-6-25014	2025/4/24	综合判定：合格。	
359	GX-B1304/21-6-25015	2025/4/24	综合判定：合格。	

360	GX-B1304/21-6-25016	2025/4/24	综合判定：合格。		
361	GX-B1309/21-6-25009	2025/4/16	所检项目合格。		
362	GX-B1500/21-6-25050	2025/4/16	综合判定：合格。		

363	GX-B1500/21-6-25051	2025/4/16	综合判定：合格。			
364	GX-B1500/21-6-25052	2025/4/16	综合判定：合格。			
365	GX-B1500/21-6-25053	2025/4/16	综合判定：合格。			

366	GX-B1309/21-6-25010	2025/4/16	所检项目合格。		
367	GX-B1500/21-6-25054	2025/4/16	综合判定：合格。		
368	GX-B1500/21-6-25055	2025/4/16	综合判定：合格。		

369	GX-B1500/21-6-25056	2025/4/16	综合判定：合格。		
370	GX-B1500/21-6-25057	2025/4/16	综合判定：合格。		
371	GX-B1310/21-6-25099	2025/4/25	符合标准要求。		

372	GX-B1310/21-6-25100	2025/4/25	符合标准要求。		
373	GX-B1310/21-6-25101	2025/4/25	符合标准要求。		
374	GX-B1310/21-6-25102	2025/4/25	符合标准要求。		

375	GX-B1310/21-6-25103	2025/4/25	符合标准要求。	
376	GX-B1310/21-6-25104	2025/4/25	符合标准要求。	
377	GX-B1310/21-6-25105	2025/4/25	符合标准要求。	

378	GX-B1310/21-6-25106	2025/4/25	符合标准要求。	 A worker in a blue uniform and red helmet is working on a metal structure, possibly a conveyor belt or a large pipe. The worker is wearing a safety harness and is focused on the task. The background shows some industrial equipment and a concrete floor. A timestamp "2025 4 18" is visible in the bottom right corner of the image.
379	GX-B1310/21-6-25107	2025/4/25	符合标准要求。	 A worker in a grey uniform and red helmet is working on a metal structure, possibly a conveyor belt or a large pipe. The worker is wearing a safety harness and is focused on the task. The background shows some industrial equipment and a concrete floor. A timestamp "2025 4 18" is visible in the bottom right corner of the image.
380	GX-B1310/21-6-25108	2025/4/25	符合标准要求。	 A worker in a blue uniform and red helmet is working on a green machine, possibly a large pump or a motor. The worker is wearing a safety harness and is focused on the task. The background shows some industrial equipment and a concrete floor. A timestamp "2025 4 18" is visible in the bottom right corner of the image.

381	GX-B1310/21-6-25109	2025/4/25	符合标准要求。	 A worker in a blue uniform and red helmet is operating a yellow machine, possibly a press or a welding station, next to a large, dark metal structure. The date stamp '2025 4 18' is visible in the bottom right corner of the image.
382	GX-B1310/21-6-25110	2025/4/25	符合标准要求。	 A worker in a blue uniform and red helmet is working on a large metal structure, possibly a part of a machine or a building. The date stamp '2025 4 18' is visible in the bottom right corner of the image.
383	GX-B1310/21-6-25111	2025/4/25	符合标准要求。	 A worker in a blue uniform and red helmet is standing next to a large metal structure, possibly a part of a machine or a building. The date stamp '2025 4 19' is visible in the bottom right corner of the image.

384	GX-B1310/21-6-25112	2025/4/25	符合标准要求。	 A worker in a blue uniform and red helmet is operating a large industrial wheel in a tunnel. The worker is looking towards the camera. The date stamp '2025 4 19' is visible in the bottom right corner of the image.
385	GX-B1310/21-6-25113	2025/4/25	符合标准要求。	 A worker in a blue uniform and red helmet is operating a large industrial wheel in a tunnel. The worker is looking towards the camera. The date stamp '2025 4 19' is visible in the bottom right corner of the image.
386	GX-B1310/21-6-25114	2025/4/25	符合标准要求。	 A worker in a blue uniform and red helmet is operating a large industrial wheel in a tunnel. The worker is looking towards the camera. The date stamp '2025 4 20' is visible in the bottom right corner of the image.

387	GX-B1310/21-6-25115	2025/4/25	符合标准要求。	 A worker in a blue uniform and red helmet is working on a large industrial machine. The worker is wearing a safety harness and is focused on the task. The machine has a large, curved, metallic component. The date stamp '2025 4 20' is visible in the bottom right corner of the image.
388	GX-B1310/21-6-25116	2025/4/25	符合标准要求。	 A worker in a white uniform and red helmet is working on a large industrial machine. The worker is wearing a safety harness and is focused on the task. The machine has a large, curved, metallic component. The date stamp '2025 4 20' is visible in the bottom right corner of the image.
389	GX-B1310/21-6-25117	2025/4/25	符合标准要求。	 A worker in a white uniform and red helmet is working on a large industrial machine. The worker is wearing a safety harness and is focused on the task. The machine has a large, curved, metallic component. The date stamp '2025 4 21' is visible in the bottom right corner of the image.

390	GX-B1310/21-6-25118	2025/4/25	符合标准要求。	
391	GX-B1310/21-6-25119	2025/4/25	符合标准要求。	
392	GX-B1500/21-6-25058	2025/4/25	综合判定：合格。	

393	GX-B1500/21-6-25059	2025/4/25	综合判定：合格。		 A worker in a grey uniform and red helmet is operating a green industrial machine. The machine has a red emergency stop button. The date 2025 04 20 is visible in the bottom right corner of the image.	
394	GX-B1500/21-6-25060	2025/4/25	综合判定：合格。		 A worker in a grey uniform and red helmet is operating a green industrial machine. The machine has a red emergency stop button. The date 2025 04 20 is visible in the bottom right corner of the image.	
395	GX-B1500/21-6-25061	2025/4/25	综合判定：合格。		 A worker in a grey uniform and red helmet is operating a green industrial machine. The machine has a red emergency stop button and a yellow warning sign. The date 2025 04 20 is visible in the bottom right corner of the image.	

396	GX-B1500/21-6-25062	2025/4/25	综合判定：合格。		 2025 04 20	
397	GX-B1500/21-6-25063	2025/4/25	综合判定：合格。		 2025 04 20	
398	GX-B1500/21-6-25070	2025/4/25	综合判定：合格。		 2025 04 19	

399	GX-B1500/21-6-25071	2025/4/25	综合判定：合格。	 2025 04 19	
400	GX-B1500/21-6-25072	2025/4/25	综合判定：合格。	 2025 04 19	
401	GX-B1500/21-6-25073	2025/4/25	综合判定：合格。	 2025 04 19	

402	GX-B1500/21-6-25074	2025/4/25	综合判定：合格。	
403	GX-B1500/21-6-25075	2025/4/25	综合判定：合格。	
404	GX-B1500/21-6-25076	2025/4/25	综合判定：合格。	

405	GX-B1309/21-6-25011	2025/4/25	综合判定：合格。		
406	GX-B1309/21-6-25012	2025/4/25	综合判定：合格。		
407	GX-B1309/21-6-25015	2025/4/25	综合判定：合格。		

408	GX-B1309/21-6-25016	2025/4/25	综合判定：合格。	
409	GX-B1305/21-6-25008	2025/4/25	综合判定：合格。	
410	GX-B1305/21-6-25009	2025/4/25	综合判定：合格。	

411	GX-B1305/21-6-25010	2025/4/25	综合判定：合格。	
412	GX-B1328/20-6-25057	2025/4/27	本次共检绝缘手套 4只, 4只绝缘手套合格。 。	
413	GX-B1328/20-6-25058	2025/4/27	本次共检全橡胶绝缘 胶靴4只, 4只全橡胶 绝缘胶靴合格。	

414	GX-B1328/20-6-25059	2025/4/27	本次共检绝缘杆2只， 2只绝缘杆合格。		
415	GX-B1451/20-6-25619~25634	2025/4/27	本次共检高压开关柜 16台, 16台高压开关柜 所检项目合格。		
416	GX-B1451/20-6-25635~25651	2025/4/27	本次共检高压开关柜 17台, 17台高压开关柜 所检项目合格。		

417	GX-B1451/20-6-25652~25662	2025/4/27	本次共检高压开关柜11台, 11台高压开关柜所检项目合格。	
418	GX-B1451/20-6-25663~25672	2025/4/27	本次共检高压开关柜10台, 10台高压开关柜所检项目合格。	
419	GX-B1313/21-6-25151	2025/4/27	所检项目合格。	

420	GX-B1328/20-6-25054	2025/4/27	本次共检绝缘手套 2只, 2只绝缘手套合格。 。		
421	GX-B1328/20-6-25055	2025/4/27	本次共检全橡胶绝缘 胶靴2只, 2只全橡胶 绝缘胶靴合格。		
422	GX-B1328/20-6-25056	2025/4/27	所检项目合格。		

423	GX-B1427/21-6-25021	2025/4/25	符合标准要求。 。	
424	GX-B1427/21-6-25022	2025/4/25	符合标准要求。 。	
425	GX-B1427/21-6-25023	2025/4/25	符合标准要求。 。	

426	GX-B1427/21-6-25024	2025/4/25	符合标准要求。 。	
427	GX-B1598/24-6-25007	2025/4/25	实测钢丝绳有效 截面积损失百分 比最大为0.43%， 小于5%为正常。	
428	GX-B1598/24-6-25008	2025/4/25	实测钢丝绳有效 截面积损失百分 比最大为0.30%， 小于5%为正常。	

429	GX-B1598/24-6-25009	2025/4/25	实测钢丝绳有效截面积损失百分比最大为0.35%，小于5%为正常。	
430	GX-B1598/24-6-25010	2025/4/25	实测钢丝绳有效截面积损失百分比最大为0.29%，小于5%为正常。	
431	GX-B1598/24-6-25011	2025/4/25	实测钢丝绳有效截面积损失百分比最大为0.15%，小于5%为正常。	

432	GX-B1598/24-6-25012	2025/4/25	实测钢丝绳有效截面积损失百分比最大为0.36%，小于5%为正常。		
433	GX-B1598/24-6-25013	2025/4/25	实测钢丝绳有效截面积损失百分比最大为0.16%，小于5%为正常。		
434	GX-B1598/24-6-25014	2025/4/28	实测钢丝绳有效截面积损失百分比最大为2.14%，小于5%为正常。		

435	GX-B1598/24-6-25015	2025/4/28	实测钢丝绳有效截面积损失百分比最大为2.43%，小于5%为正常。		
436	GX-B1598/24-6-25016	2025/4/28	实测钢丝绳有效截面积损失百分比最大为2.29%，小于5%为正常。		
437	GX-B1309/21-6-25017	2025/4/29	所检项目合格。		

438	GX-B1309/21-6-25018	2025/4/29	所检项目合格。			
439	GX-B1500/21-6-25077	2025/4/29	综合判定：合格。			
440	GX-B1500/21-6-25078	2025/4/29	综合判定：合格。			


441	GX-B1500/21-6-25079	2025/4/29	综合判定：合格。	
442	GX-B1500/21-6-25080	2025/4/29	综合判定：合格。	
443	GX-B1500/21-6-25081	2025/4/29	综合判定：合格。	

444	GX-B1500/21-6-25082	2025/4/29	综合判定：合格。	
445	GX-B1500/21-6-25083	2025/4/29	综合判定：合格。	
446	GX-B1500/21-6-25084	2025/4/29	综合判定：合格。	


447	GX-B1500/21-6-25085	2025/4/29	综合判定：合格。	
448	GX-B1500/21-6-25086	2025/4/29	综合判定：合格。	
449	GX-B1500/21-6-25087	2025/4/29	综合判定：合格。	

450	GX-B1324/21-6-25044~25045	2025/4/30	所检项目合格。	
451	GX-B1598/24-6-25024	2025/4/30	实测钢丝绳有效截面积损失百分比最大为1.03%，小于5%为正常。	
452	GX-B1598/24-6-25025	2025/4/30	实测钢丝绳有效截面积损失百分比最大为1.37%，小于5%为正常。	

453	GX-B1598/24-6-25026	2025/4/30	实测钢丝绳有效截面积损失百分比最大为1.17%，小于5%为正常。	
454	GX-B1598/24-6-25027	2025/4/30	实测钢丝绳有效截面积损失百分比最大为1.08%，小于5%为正常。	
455	GX-B1598/24-6-25028	2025/4/30	实测钢丝绳有效截面积损失百分比最大为0.57%，小于5%为正常。	


456	GX-B1598/24-6-25029	2025/4/30	实测钢丝绳有效截面积损失百分比最大为0.98%，小于5%为正常。		
457	GX-B1598/24-6-25030	2025/4/30	实测钢丝绳有效截面积损失百分比最大为0.44%，小于5%为正常。		
458	GX-B1598/24-6-25031	2025/4/30	实测钢丝绳有效截面积损失百分比最大为1.64%，小于5%为正常。		

459	GX-B1598/24-6-25032	2025/4/30	实测钢丝绳有效截面积损失百分比最大为1.79%，小于5%为正常。	
460	GX-B1598/24-6-25033	2025/4/30	实测钢丝绳有效截面积损失百分比最大为1.63%，小于5%为正常。	
461	GX-B1598/24-6-25034	2025/4/30	实测钢丝绳有效截面积损失百分比最大为1.77%，小于5%为正常。	

462	GX-B1598/24-6-25035	2025/4/30	实测钢丝绳有效截面积损失百分比最大为1.44%，小于5%为正常。	
463	GX-B1598/24-6-25036	2025/4/30	实测钢丝绳有效截面积损失百分比最大为1.93%，小于5%为正常。	
464	GX-B1598/24-6-25037	2025/4/30	实测钢丝绳有效截面积损失百分比最大为0.40%，小于5%为正常。	

465	GX-B1598/24-6-25038	2025/4/30	实测钢丝绳有效截面积损失百分比最大为0.40%，小于5%为正常。	
466	GX-B1598/24-6-25039	2025/4/30	实测钢丝绳有效截面积损失百分比最大为0.39%，小于5%为正常。	
467	GX-B1598/24-6-25040	2025/4/30	实测钢丝绳有效截面积损失百分比最大为0.42%，小于5%为正常。	

468	GX-B1598/24-6-25041	2025/4/30	实测钢丝绳有效截面积损失百分比最大为1.24%，小于5%为正常。	
469	GX-B1598/24-6-25042	2025/4/30	实测钢丝绳有效截面积损失百分比最大为1.30%，小于5%为正常。	
470	GX-B1598/24-6-25017	2025/4/30	实测钢丝绳有效截面积损失百分比最大为0.60%，小于5%为正常。	

471	GX-B1598/24-6-25018	2025/4/30	实测钢丝绳有效截面积损失百分比最大为0.81%，小于5%为正常。	
472	GX-B1598/24-6-25019	2025/4/30	实测钢丝绳有效截面积损失百分比最大为0.72%，小于5%为正常。	
473	GX-B1598/24-6-25020	2025/4/30	实测钢丝绳有效截面积损失百分比最大为0.71%，小于5%为正常。	

474	GX-B1598/24-6-25021	2025/4/30	实测钢丝绳有效截面积损失百分比最大为1.30%，小于5%为正常。	
475	GX-B1598/24-6-25022	2025/4/30	实测钢丝绳有效截面积损失百分比最大为1.11%，小于5%为正常。	
476	GX-B1598/24-6-25023	2025/4/30	实测钢丝绳有效截面积损失百分比最大为1.42%，小于5%为正常。	

477	GX-B1350/21-6-25022	2025/4/30	所检项目合格。	
478	GX-B1322/21-6-25218~25222	2025/4/30	本次共检验电力电缆5条，5条电力电缆所检项目合格。	
479	GX-B1313/21-6-25160~25162	2025/4/30	本次共检电力变压器3台，3台电力变压器所检项目合格。	

480	GX-B1495/20-6-25675~25682	2025/4/30	本次共检高压开关柜8台，8台高压开关柜所检项目合格。	
-----	---------------------------	-----------	----------------------------	---